

THE SAFETY BOX

A newsletter dedicated to keeping our children safe

Louisiana Department of Justice ◆James D. "Buddy" Caldwell, Attorney General ◆Consumer Protection Section ◆ Fall 2014/Winter 2015

This newsletter is printed quarterly in accordance with the **Louisiana Children's Product Act, La. R.S. 46:2701-2711.** For more information on recalled children's products, consumers may visit our website at www.agbuddycaldwell.com, click on "News and Publications," or call our toll-free **CONSUMER INFO LINE** at **(800) 351-4889**. Information about child product recalls and toy hazard recalls included in this newsletter was received from the **Consumer Product Safety Commission (CPSC)**. Consumers may visit their website at www.cpsc.gov for product recall information and product safety information. The recall information included in this newsletter is for October 2014 through February 2015.

TOY PRODUCT RECALLS

PRODUCT/FIRM: Fly Boy Airplane Rocker

BRAND/MODEL: The Levels of Discovery Fly Boy Airplane Rockers are wooden children's rocking chairs.



The chairs have red wooden spindle frames and red wing-shaped arm rests. Hinged to the front of the chair is a light blue U-shaped airplane steering yoke and a console with red wooden knobs with blue painted circular controls and a red propeller. The light blue seat of the chair has a navy blue fabric seat cushion and seat back with red buttons. "FLY BOY" is

printed on the top frame of the seat back with a printed picture of a red airplane. The chairs weigh about 17 pounds and measures 29 inches tall by 16 inches deep by 23 inches wide. Model number RAB00038 is printed on the underside of the rocker seat.

PROBLEM: The red wooden knobs on the rocker's steering panel console can detach, posing a small parts choking hazard to young children.

REMEDY: Consumers should immediately take the recalled rocker away from young children and contact the firm to receive a replacement console

PRODUCT/FIRM: K.J. Sportswear Pajamas

BRAND/MODEL: This recall involves children's one-



piece and two-piece Thor pajama sets. The children's one-piece 94% polyester and 6% spandex with "Thor" printed on the center front in three different color patterns: blue and white, red and white, and pink and black. The children's two-piece,

long sleeve and pant pajama set is 94% polyester and 6% spandex with "Thor" printed on the center front in three different color patterns: blue and white, red and white, and pink and black. The pajamas were sold in sizes 6 to 12 months, 12 to 18 months and 18 to 24 months through youth large. This recall includes both pajama styles with these tracking numbers on the back of the neck label: 728141, 995755, 995756, 995757 and 995758.

PROBLEM: The pajamas fail to meet federal flammability standards for children's sleepwear, posing a risk of burn injury to children.

REMEDY: Consumers should immediately take the recalled pajamas away from children, stop using them and return them to K.J. Sportswear California for a full refund.

PRODUCT/FIRM: Animated Toy by Giggles International

BRAND/MODEL: This recall involves Giggles International Animated Sing-Along Monkey toys. The monkey is made of brown and beige plush material and is about 9 inches tall. The toy is designed to hold a song book titled "5 Little Monkeys" and to sing the song when



activated. A red music note is on the bottom of the monkey's right foot and the face of a child with its hands covering its eyes are on the bottom of the money's left foot. Recalled sing-along monkeys were manufactured between 6/7/2014 and 7/5/2014 and have batch code GP1410028. The manufacture date in the M/D/YYYY format and

batch code are printed on the bottom of a white fabric label attached near the base of the monkey's tail. The monkey toys came in a tan colored box with words "Animated Sing-Along Monkey," "Sing along with me!" and "I play peek-a-boo with you!" on the front. The age advisory "For ages 3+" and the warning that batteries are included are also on the front of the box.

PROBLEM: The battery compartment can reach temperatures up to 230 degrees Fahrenheit, posing a burn hazard.

REMEDY: Consumers should immediately take the animated monkey away from children, remove the batteries and return the toy to any Cracker Barrel Old Country Store or contact Giggles International for a full refund.

PRODUCT/FIRM: Airplane and butterfly push toys by LS Import

BRAND/MODEL: This recall involves plastic airplane and butterfly push toys. The airplane push toy is red and



has a blue, yellow and red rotor above the cockpit's canopy and eyelids on the nose of the airplane that open and shut when the toy is been pushed on the floor. The airplane push toy has a pink plastic rod with a handle that connects to the

back of the toy to push it. The butterfly push toy's body is yellow with pink wings and has a pink plastic ball at the end of each of two antennas and a pair of wings that flap up and down when the toy is been pushed on the floor. The butterfly push toy has a green plastic rod with a handle that connects to the back of the toy to push it.

PROBLEM: The wheels of the airplane and the balls at the tip of the butterfly's antenna can detach, posing a choking hazard to young children.

REMEDY: Consumers should immediately take the recalled toys away from children and contact LS Import for a full refund.

PRODUCT/FIRM: Auto Carrier Toy Sets by Family Dollar

BRAND/MODEL: This recall involves a plastic toy truck



with a plastic case that holds 6 die-cast metal toy cars in assorted colors. The truck is 14 inches long x 3 inches wide x 5

inches high. The cab of the truck comes in black, blue or red. The package is labeled as "Tough Treadz Auto Carrier" and has a white sticker in the upper right-hand corner with "\$5" and "SKU 1004247" printed in red. The UPC code appears on a label on the back stating "Made in China." The following UPC codes are included in this recall: 678565114083, 678565114090, 678565114106.

PROBLEM: The die-cast metal cars can have sharp edges that pose a laceration hazard.

REMEDY: Consumers should immediately stop using the recalled toy sets, take them away and return them to any Family Dollar Stores location for a full refund.

PRODUCT/FIRM: The PouchPop Topper by Performance Packaging

BRAND/MODEL: The recalled PouchPops are silicone toppers that screw onto a baby food pouch that allow infants to feed themselves. The PouchPops were sold in



a four-pack of four colors including green, orange, red and yellow and have a cylinder-shaped tube stem that attaches to a round base. The pouch toppers have a

"SipP" logo and smiley face embossed on the circular base.

PROBLEM: The tube of the pouch topper that screws onto the food pouch can separate from the round base, posing a choking hazard to young children.

REMEDY: Consumers should immediately stop using the recalled PouchPop toppers and contact Performance Packaging for instructions on receiving a free replacement product or full refund.

CHILD PRODUCT RECALLS

PRODUCT/FIRM: Youth Loungewear Pants by M&M **BRAND/MODEL:** This recall involves youth loungewear pants. The youth loungewear pants came in two prints,



one with an allover boxed M&M'S® character print and the second with an allover M&M'S® candy print. Both youth loungewear pants are 100% cotton and were sold in youth sizes small through XL. The recalled garments have a label sewn inside the waistband with the product's identification number that includes the last four digits as the date of manufacture in MMYY format. The

recalled youth loungewear pants have identification numbers ending in 0711, 0212, 1112, 0313, 0413 or 0713.

PROBLEM: The youth loungewear pants fail to meet federal flammability standards for children's sleepwear, posing a risk of burn injury to children.

REMEDY: Consumers should immediately take the recalled youth loungewear pants away from children, stop using them and return them to M&M'S World[®] for a full refund.

PRODUCT/FIRM: Kid's Korner Hooded Sweatshirts **BRAND/MODEL:** This recall involves Kids Korner brand



boy's, girl's and toddler's cotton/poly blend fleece zipper hooded sweatshirts with a front zipper, two front pockets and knit ribbing around the wrists and waist. The sweatshirts were sold in 62 different prints and solid colors in infant, toddler to children's size 4. The size can be found on a label sewn into the back seam of the neck. A white label sewn into the

lower left inside seam reads Inter-American Products, Lahore, Pakistan and has style number ending in 8025, 8025P, 8128, 8128P, 8174P, 8251, 8326 or 8326P. Also on the label are the following manufacture dates: March 2014, April 2014, June 2014 or November 2014 and batch numbers: 1, FLC-P5, FLC-P6 or FLC-P8. To view photos of all recalled sweatshirts, visit the Recall Alerts section on the firm's web site.

PROBLEM: The sweatshirt zipper pull can detach, posing a choking hazard to young children.

REMEDY: Consumers should immediately take the sweatshirt away from young children and return it to the place of purchase for a full refund. Consumers without a sales receipt will be refunded current retail price.

PRODUCT/FIRM: K.J. Sportswear Pajamas **BRAND/MODEL:** This recall involves children's one-piece and two-piece Thor pajama sets. The children's



one-piece 94% polyester and 6% spandex with "Thor" printed on the center front in three different color patterns: blue and white, red and white, and pink and black. The children's two-piece, long-sleeve and pant pajama set is 94% polyester and 6%

spandex with "Thor" printed on the center front in three different color patterns: blue and white, red and white, and pink and black. The pajamas were sold in sizes 6 to 12 months, 12 to 18 months and 18 to 24 months through youth large. This recall includes both pajama styles with these tracking numbers on the back of the neck label: 728141, 995755, 995756, 995757 and 995758.

PROBLEM: The pajamas fail to meet federal flammability standards for children's sleepwear, posing a risk of burn injury to children.

REMEDY: Consumers should immediately take the recalled pajamas away from children, stop using them and return them to K.J. Sportswear California for a full refund.

PRODUCT/FIRM: KTM North America Pajamas **BRAND/MODEL:**. This recall involves children's onesies and two-piece KTM motocross pajamas. The Baby



Racing Body onesies are 95% cotton and 5% elastane and were sold in three prints. One is orange with white sleeves and the KTM brand logo on the left chest. The second is white and orange with the KTM brand logo in bold orange printed on the center front of the

chest and on the left and right hip. The third onesie is yellow with orange and black detailing and the KTM brand logo printed on the left. All onesies are long-sleeved and have snap closures from the neck to the left ankle and were sold in sizes 18 months to 2T.

The two-piece, long-sleeve and pant pajama sets are 100% cotton and were sold in two prints. The Kids Racing Gear pajama is white with black, orange and grey detailing on the top and pant with a black elastic waistband and KTM printed on the left side of the chest.

This set was sold in sizes 2T through 5T. The Kids Gravity Gear pajama two-piece set is white with blue, and orange detailing on the top and pant with an elastic waistband in orange and KTM printed on the left side of the chest and on the right hand wrist. This set was sold in sizes XXS through L

PROBLEM: The pajamas fail to meet federal flammability standards for children's sleepwear, posing a risk of burn injuries to children.

REMEDY: Consumers should immediately take the recalled pajamas away from children, stop using them and return them to KTM North America, Inc. for a full refund

PRODUCT/FIRM: Dream on Me Bassinet

BRAND/MODEL: This recall involves the 2-in-1 Bassinet to Cradle, sold in pink, blue, green, and white. The



bassinet has metal frame supports and fabric sides with a removable half-canopy on the top. The frame can also be adjusted with two rocking legs on each end of the bassinet. It is designed with fabric handles and the option to remove the bassinet from the frame to use the bassinet portion as a "by the bed" sleeper product. The recalled model numbers are 439-A.

439-B, 439-G, 439-P and 439-W and can be found on a tag which is located under the mattress pad of the bassinet. This tag is a removable tag you see in the store but is removed prior to use.

PROBLEM: The wire supports on the sides of the bassinet can disconnect causing the fabric sides to lower; posing a risk that infants can fall out or become entrapped and suffocate..

REMEDY: Consumers should immediately stop using the product and contact Dream On Me to obtain a free repair. In the meantime, parents are urged to find an alternate, safe sleeping environment for the child, such as a crib that meets current safety standards or play yard depending on the child's age.

PRODUCT/FIRM: Scott Evo Bicycle Helmet

BRAND/MODEL: The helmets have the brand name "SCOTT" printed on the outer shell of the helmet on the



left side. For the Vanish Evo black and grey helmets, the lettering is black; for the Vanish Evo white and grey helmets, the lettering is white. The following serial number ranges are included in this recall: 2014-06/009359 through 2014-09/027210. The serial number is

printed on a white sticker inside the back of the helmet.

PROBLEM: The bicycle helmets do not comply with the impact requirements of the CPSC safety standards for bicycle helmets.

REMEDY: Consumers should immediately stop using the bicycle helmet and take it to an authorized SCOTT dealer for a refund of the purchase price.

PRODUCT/FIRM: Marin Children's Bikes

BRAND/MODEL: This recall involves Marin 2014 model



MBX 50 and Tiny Trail boys and girls bicycles with 16-inch knobby tires. The single speed bicycles have high-rise handlebars and training wheels. The boy's bicycles were sold in red and have serial number HA14980XXXXXX. The girl's

bicycles were sold in purple and have serial number HA14982XXXXXX. Serial numbers are printed on a foil label affixed to the underside of the base of the down tube. "Marin" is printed on the seat and the downtube. "Tiny Trail" or "MBX 50" is printed on the bicycles chain guard.

PROBLEM: The handlebars can loosen or separate during use. This can cause the rider to lose control and/or crash, posing the risk of injury.

REMEDY: Consumers should immediately stop using the recalled bicycle and contact Marin for a replacement handlebar stem.

PRODUCT/FIRM: Mima Moon 3-in-1 High Chairs **BRAND/MODEL:** This recall includes Moon model 3-in-1 high chairs which adjust to a newborn, high and junior



chair with a unique design consisting of a base with two feet supporting a single post that holds up the seat in a clear shell. The shell has a white inner seat with a removable seat pad in white, camel or black. The high chair measures about 3 feet tall when in its highest position. There is a "Mima" logo where the metal post

attaches to the base to the seat. There is also a "Moon" logo on the inside of the feet that form the base of the high chair. The serial and model numbers are located on a sticker on the inside of one of the two feet that form the base of the high chair.

PROBLEM: The high chair seat can loosen and dislodge, allowing the seat and child to fall. The chair can also fall onto a child crawling underneath the seat, posing an impact hazard to the child.

REMEDY: Consumers should stop using the high chair immediately and contact Mima to receive a free replacement upper chair section or instructions on receiving a refund.

PRODUCT/FIRM: Lazy One Children's Pajamas



BRAND/MODEL: This recall involves 100% polyester Lazy One children's sleepwear garments, including footed pajamas and two robes. The one-piece "footeez" style footed zip-up pajama is beige with a red, pink, blue and yellow owl print with the wording "I'm OWL yours." It

has blue trim at the neck, cuff and right-hand side single pocket. The pajama has a foot-to-neck zipper, non-slip soles and a rear opening on the behind. It was sold in sizes children's small through extra-large. One of the

recalled robes is pink with moose graphics and "Don't Moose With Me" printed on it. It has solid green trim, two front pockets and belt. The second robe is red with printed moose graphics and solid black trim, two front pockets and belt. Both robes were sold in sizes 4T through 14. "Lazy One", the size and "Made in China" are printed on the garments' neck label. Garments with "Flame Resistant" printed on the neck label are not included in this recall.

PROBLEM: The footed pajamas and robes fail to meet the federal flammability standard for children's sleepwear, posing a burn hazard to children.

REMEDY: Consumers should immediately take the recalled pajamas and robes away from children and return them to Lazy One for a free replacement garment, including shipping.

PRODUCT/FIRM: VYSSA crib mattress by IKEA **BRAND/MODEL:** This recall involves IKEA VYSSA style crib mattresses with the following five model names:



VACKERT, VINKA, SPELEVINK, SLÖA and SLUMMER. The involved mattresses were manufactured on May 4, 2014 or earlier. An identification label attached to the mattress cover has the date of manufacture in Month-DD-YYYY format and the VYSSA model name. A gap between the

mattress and crib ends larger than two finger width is an indication of the defective mattress.

PROBLEM: The crib mattresses could create a gap between the mattress and crib ends larger than allowed by federal regulations, posing an entrapment hazard to infants.

REMEDY: Consumers should inspect the recalled mattress by making sure there is no gap larger than the width of two fingers between the ends of the crib and the mattress. If any gap is larger, customers should immediately stop using the recalled mattresses and return it to any IKEA store for an exchange or a full refund.

PRODUCT/FIRM: Star Ride Kids Children's Pajamas **BRAND/MODEL:** This recall involves Star Ride Kids



girl's pajama sets. The recalled pajamas are made of polyester and sold in sizes 4 through 14. The pajama sets consist of polar fleece pants with a bow and elastic at the waist and a jersey two-piece long-sleeve shirt. Style reference number 5217 or 5250 is on a label in the side seam of each shirt. "Star Ride Taking It To The Next Level" is on a label

in the waistband of each pair of pants. The logo "Star Ride" is printed on the inside back of the neck of each shirt. Some shirts have a hangtag on the wrist with the words "flame resistant sleepwear." The sets were sold in the following combinations:

PROBLEM: The pajamas fail to meet federal flammability standards for children's sleepwear, posing a risk of burn injuries to children.

REMEDY: Consumers should immediately take the recalled pajamas away from children, stop using them and return them to the place of purchase for a full refund.

PRODUCT/FIRM: Croker Kids Fleece by James Trading **BRAND/MODEL:** This recall involves James Trading Group's Croker Kids brand Gaelic Athletic Association



(GAA) licensed fleece hoodies. The hoodie has a full zippered front and 3-tone color panels of green, white and blue, with GAA embroidery on the left and right chest and on the hood. The word Ireland is printed on the back across the shoulders. The fabric is 75% cotton and 25% polyester. They were sold in kids sizes "2YR" through "12YR" shown on a hang tag and on

the tag sewn into the neck. Model number GA2002 is on a hang tag.

PROBLEM: The sweatshirts have a drawstring around the neck area which poses a strangulation hazard to children. Drawstrings can become entangled or caught on playground slides, hand rails, school bus doors or other moving objects, posing a significant strangulation and/or entanglement hazard to children. In February 1996, CPSC issued guidelines about drawstrings in children's upper outerwear. In 1997, those guidelines were incorporated into a voluntary standard. Then, in July 2011, based on the guidelines and voluntary standard, CPSC issued a federal regulation. CPSC's actions demonstrate a commitment to help prevent children from strangling or getting entangled on neck and waist drawstrings in upper outerwear, such as jackets and sweatshirts.

REMEDY: Consumers should immediately take the jackets away from children and remove the drawstring from the jacket to eliminate the hazard or return it to the place of purchase for a full refund.

PRODUCT/FIRM: Ski-Doo and Can-Am Hoodies by BRP

BRAND/MODEL: This recall involves 14 styles of Ski-Doo or Can-Am kids' hooded sweatshirts for boys and



girls. They were sold in kids' sizes 2 through 12. The hoodies are cotton/polyester blend.

There is a drawstring in the hood of the garment. Colors include raspberry, yellow, heather, charcoal gray and black. "Ski Doo" or "Can-Am" is printed on

the front. Recalled style numbers

include: 286485, 453215, 453265, 453320, 453321, 453375, 453376, 453464, 453618, 453658, 453660, 453661, 453707 and 453708. The style numbers indicating the different graphic treatments are printed on the white care label that is sewn into the neck and side of the garment.

PROBLEM: The hoodies have a drawstring around the neck area which poses a strangulation hazard to children. Drawstrings can become entangled or caught on playground slides, hand rails, school bus doors or other moving objects, posing a significant strangulation and/or entanglement hazard to children. In February 1996, CPSC issued guidelines about drawstrings in children's upper outerwear. In 1997, those guidelines were incorporated into a voluntary standard. Then, in July 2011, based on the guidelines and voluntary standard, CPSC issued a federal regulation. CPSC's actions demonstrate a commitment to help prevent children from strangling or getting entangled on neck and waist drawstrings in upper outerwear, such as jackets and sweatshirts.

REMEDY: Consumers should immediately take the hoodie away from kids and remove the drawstring from the sweatshirt to eliminate the hazard or return it to an authorized BRP dealer for a full refund.

PRODUCT/FIRM: Bicycle Helmets by UVEX Sports **BRAND/MODEL:** This recall involves seven models of



UVEX helmets. The helmets come in a variety of colors with different colored chin straps. The helmets have a model number inside the helmet under the fitting pad on the top right side. The affected helmet model numbers are XB017, XB022, XB025, XB027, XB032, XB036

and XB038.

PROBLEM: The anchor for the helmet's chinstrap can fail, causing the helmets to slide off the head, posing a head injury hazard. The bicycle helmets also do not comply with the impact requirements of the CPSC safety standards for bicycle helmets.

REMEDY: Consumers should stop using the helmets and contact UVEX for a free compliant helmet or a refund of the purchase price.

PRODUCT/FIRM: Dream On Me Play Yards **BRAND/MODEL:**. The recall includes Dream On Me Incredible two-level deluxe adjustable height play yards



with model number starting with 436A, 436B, 436G, 436O, 436P and 436R. The play yards, made with a steel, powder-coated frame base with rolling, hooded casters, have a fabric and mesh covering that comes in a variety of colors. The play yard includes a


changing top, a toy bar with soft toys for entertainment, a side pocket for storage and a carrying case. "Dream On Me" is printed on the bottom left-hand side outside of the product. The model number is printed on a label attached to the play yard's mattress. The play yard can be folded for storage

PROBLEM: The play yard's rails can collapse, presenting a strangulation hazards to young children.

REMEDY: Consumers should immediately stop using the recalled play yards and contact Dream On Me to receive a free repair kit.

PRODUCT/FIRM: Leatherman Leap multi-tool

BRAND/MODEL: This recall involves the Leatherman Leap multi-purpose tool that was designed for users age



nine and up. The multi-tool has a green, blue or red plastic casing with two screws, one on each handle of the tool. It consists of combination needlenose and regular pliers, wire cutters, wood saw, ruler, tweezers, soda bottle opener, optional 420HC (high carbon stainless steel) knife blade, scissors, phillips screwdriver, and small and medium slotted screwdrivers. The words

slotted screwdrivers. The words Leatherman and LeapTM appear on one side of the multitool.

PROBLEM: The lock mechanism on the optional knife blade can inadvertently release the blade, posing a laceration hazard.

REMEDY: Consumers should not install the optional knife blade or should immediately stop using the multitool with the installed optional knife. Consumers should contact Leatherman for a free replacement multi-tool, including shipping.

PRODUCT/FIRM: Graco Strollers

BRAND/MODEL: This recall includes eleven Graco and Century-branded strollers with model names Aspen,



Breeze, Capri, Cirrus, Glider, Kite, LiteRider, Sierra, Solara, Sterling and TravelMate. All models are a single-occupant stroller with an external sliding fold-lock hinge on each side and a one-hand fold release mechanism on the handle. Strollers with a manufacture date from August 1, 2000 to September 25, 2014 are included in the recall. Model numbers and the date of

manufacture are printed on the white label located at the bottom of the stroller leg just above the rear wheel.

PROBLEM: The folding hinge on the sides of the stroller can pinch a child's finger, posing a laceration or amputation hazard.

REMEDY: Contact Graco immediately for a free repair kit. Repair kits will be available from the firm at the beginning of December 2014. While waiting for a repair kit, caregivers should exercise extreme care when unfolding the stroller to be certain that the hinges are firmly locked before placing a child in the stroller. Caregivers are advised to immediately remove the child from a stroller that begins to fold to keep their fingers from the side hinge area.

PRODUCT/FIRM: Hoppe's Semi-Auto Gun Bore Cleaner **BRAND/MODEL:** This recall involves Hoppe's Semi-Auto Gun Bore Cleaner. This product is packaged in a brown 5 ounce plastic bottle with a blue and yellow label



and black cap. The recalled item number is SA904 and can be found above the UPC code on the label.

PROBLEM: Bottles have a child-resistant cap that can become loose. Chemicals in this product can cause skin irritation, internal injury or death if ingested.

REMEDY: Consumers should immediately discontinue use of the product, ensure that the cap is secured on the bottle, keep out of the reach and sight of children and contact Hoppe's for a free replacement product and disposal instructions.

PRODUCT/FIRM: "Hello Kitty® Birthday Lollipop" Whistles

BRAND/MODEL: The recalled whistles are red and were included in a plastic Hello Kitty figurine holding a



pink heart-shaped lollipop. The whistle can be removed and used to make sounds by inhaling or exhaling through the mouthpiece. When closed, the figurine measures about 3 inches in height and width and 1 3/4 inches in depth. The whistle measures about 1 3/4 inches in height and width and 3/4 inches in depth. A

picture of Hello Kitty appears on both sides of the whistle. The text "©1976, 2014 SANRIO CO., LTD." appears above Hello Kitty's face on the whistle, and "Made for McDonald's China CCW Chine" appears below Hello Kitty's face on the whistle. The bag in which the toy is packaged includes the text "Hello Kitty® Birthday Lollipop" and the number "6" in the upper right corner.

PROBLEM: Components inside of the whistle can detach, posing choking and aspiration hazards to young children.

REMEDY: Consumers should immediately take the whistle away from children and return it to any McDonald's for a free replacement toy and either a yogurt tube or a bag of apple slices.

PRODUCT/FIRM: Just Like Home Toy Toaster Sets **BRAND/MODEL:** The recall includes the Just Like Home brand toy toaster sets. The teal blue plastic toy



toaster has silver trim around the slice opening on top, with an orange slider handle on the side and orange 3-dimensional adjustment knob outlined with orange dots in a half moon shape on the face of the toaster in the left bottom corner. "Just like home" is printed in

white on the front right bottom corner of the toaster. The toaster measures about 4 inches in height by 5-1/2 inches in length by 2 inches in width. The toaster set was sold with two plastic toast slices and two plastic half bagel slice accessories. Model number 5F60589 is printed on a white label on the bottom of the toaster and

above the UPC bar code in the lower right hand corner of the product packaging.

PROBLEM: The plastic toast, under pressure, can crack and break into small pieces creating sharp edges and posing a choking hazard.

REMEDY: Consumers should immediately take this product away from children and return it to any Toys R Us to receive a full refund.

PRODUCT/FIRM: Koala Children's Sandals by Toys R

Us

BRAND/MODEL: This recall involves Koala Baby girl's



plastic sandals with butterfly wings attached to the toes with rhinestones and hard or soft cork-type soles. Sandal colors include white or combination pink, gold and blue. They were sold in baby sizes 0 to 3 and girl's sizes 2 to 10. "Koala Baby" and the size are printed on the soles. White soft-soled sandals have model number GNL

43633BR and item number 795267 printed on a tag sewn into the sandal's ankle strap. White hard-soled sandals have model number GNL 43706BR and item number 795313. Combination pink, gold and blue soft-soled sandals have model number GNL 43634BR and item number 795275. Combination pink, gold and blue hard-soled sandals have GNM 41761BR and item number 845795.

PROBLEM: The butterfly wings on the children's sandals can rip and detach, posing a choking hazard to young children.

REMEDY: Consumers should immediately take the recalled sandals away from young children and return the sandals to any Toys R Us or Babies R Us for a full refund.

QUESTIONS?

Joshua Hollins
Office of the Attorney General
Consumer Protection Section
P.O. Box 94005
Baton Rouge, LA 70804-9005
(225) 326-6400 (phone)
www.agbuddycaldwell.com
hollinsj@ag.state.la.us

For information on the new crib safety standards, please visit www.cpsc.gov.

To join the Safety Box Mailing List, contact the Department of Social Services (DSS) at (225) 342-9905.

Note: The daycare facility must be registered with DSS to join the Safety Box Mailing List.

This public document is published at a total cost of \$2,716.09. Two thousand one hundred and fifty (2,150) copies of this public document were published in this first printing at a cost of \$1,429.17. The total cost of all printings of this document including reprints is \$2,716.09. This document was printed for the Louisiana Department of Justice by Employment Development Services, Inc., P.O. Box 15447, Baton Rouge, Louisiana 70895-5447 to educate consumers on child safety recalls. This material was printed in accordance with standards for printing by state agencies established pursuant to R.S. 43:31. Printing of this material was purchased in accordance with the provisions of Title 43 of the Louisiana Revised Statutes.

Louisiana Attorney General's Office Public Protection Division Consumer Protection Section P.O. Box 94005 Baton Rouge, LA 70804-9005



A newsletter dedicated to keeping our children safe.